






 3801	S 3481 C 3 H 69.70 W71.80 10/01/2001 V 2.0K JEF	 3802	S 3480 C 3 H 69.70 W71.40 10/01/2001 V 2.0K JEF	 3803	S 4820 C 2 H 60.20 W58.70 10/01/2001 V 2.0K JEF	 3804	S 4201 C 4 H 67.90 W78.80 10/01/2001 V 2.0K JEF
 3805	S 2797 C 3 H 57.10 W63.60 10/01/2001 V 2.0K JEF	 3806	S 3282 C 5 H 62.50 W55.20 10/01/2001 V 2.0K JEF	 3807	S 5104 C 3 H 66.10 W78.00 10/01/2001 V 2.0K JEF	 3808	S 3871 C 5 H 69.70 W76.90 10/01/2001 V 2.0K JEF
 3809	S 4486 C 6 H 63.40 W80.60 10/01/2001 V 2.0K JEF	 3810	S 2749 C 4 H 39.30 W81.00 10/01/2001 V 2.0K JEF	 3811	S 2662 C 4 H 82.20 W57.00 10/01/2001 V 2.0K JEF		

**BONUS
EMBROIDERY
DESIGNS**

JANOME
Embroidery
STARTER KIT