




	S 3329 C 5 H 69.10 W29.50 10/01/2001 V 2.0K JEF		S 2234 C 4 H 44.20 W24.40 10/01/2001 V 2.0K JEF		S 1652 C 5 H 37.70 W15.20 10/01/2001 V 2.0K JEF		S 1474 C 3 H 41.20 W30.30 10/01/2001 V 2.0K JEF
	S 1784 C 5 H 29.40 W29.80 10/01/2001 V 2.0K JEF		S 3557 C 3 H 64.40 W42.90 10/01/2001 V 2.0K JEF		S 2709 C 4 H 33.20 W45.50 10/01/2001 V 2.0K JEF		S 2673 C 2 H 57.40 W28.50 10/01/2001 V 2.0K JEF
	S 4633 C 4 H 80.80 W58.30 10/01/2001 V 2.0K JEF		S 1720 C 2 H 60.70 W19.50 10/01/2001 V 2.0K JEF		S 2080 C 1 H 54.40 W37.30 10/01/2001 V 2.0K JEF		S 2116 C 4 H 30.70 W79.40 10/01/2001 V 2.0K JEF
	S 1793 C 4 H 24.50 W83.40 10/01/2001 V 2.0K JEF		S 3288 C 2 H 63.10 W51.00 10/01/2001 V 2.0K JEF		S 7228 C 4 H 140.70 W73.00 10/01/2001 V 2.0K JEF		

**BONUS
EMBROIDERY
DESIGNS**

JANOME
Embroidery
STARTER KIT